

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/02/2022

Submitted Date:

02/02/2022

Document Number:

701102618

FIELD INSPECTION FORM

Loc ID 314351 Inspector Name: LONGWORTH, MIKE On-Site Inspection 2A Doc Num: _____

Status Summary:
 THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:
10 Number of Comments
6 Number of Corrective Actions
 Corrective Action Response Requested

Operator Information:
 OGCC Operator Number: 10654
 Name of Operator: LASSO OIL & GAS LLC
 Address: 3021 RIDGE RD #156
 City: ROCKWALL State: TX Zip: 75032

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Rosenberg, Kelly		kelly.rosenberg@state.co.us	
, Engineering		dnr_cogccengineering@state.co.us	All engineering
Pesicka, Conor		conor.pesicka@state.co.us	
Boulger, Levin	970-509-0256	lboulger@31operating.com	
Freeman, Kris	(254) 717-0435	kfreeman@31operating.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
228507	WELL	SI	02/01/2019	OW	103-05377	SMITH, M V 35	SI

General Comment:

COGCC Follow Up Inspection Report Summary
 Follow up to 12/28/2020 inspection # 700404820
 Uncorrected action item(s)
 • Last recorded production January 2019. No MIT in COGCC records.
 During this inspection the following compliance issues were observed:
 • Sticker with operator phone number is damaged. Nearest road to access location not posted.
 • Api # not posted on well sign.
 • Dead weed debris covering location and inside of tank berm.
 • No braden access.
 • Weeds growing inside of tank berm. Erosion rill running into tank berm from cutslope.
 A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

Location			
Lease Road:			
Type	Access		
comment:	Access road is not maintained.		
Corrective Action:		Date:	
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Api # not posted on well sign.		
Corrective Action:	Install sign to comply with Rule 605.d.	Date:	05/06/2022
Type	BATTERY		
Comment:	Sticker with operator phone number is damaged. Nearest road to access location not posted.		
Corrective Action:	Install sign to comply with Rule 605.e.	Date:	05/06/2022
Emergency Contact Number:			
Comment:	911		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	DEBRIS		
Comment:	Dead weed debris covering location and inside of tank berm.		
Corrective Action:	Comply with Rule 606	Date:	02/19/2022
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Equipment:			
Type:		#	corrective date
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked		# 3	
Comment:			
Corrective Action:		Date:	
Type: Bradenhead		# 1	
Comment:	No braden access.		

Corrective Action:	Install appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1), (2)	Date:	02/15/2022
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth		Walls Insufficient	Base Insufficient	Inadequate
Comment:	Weeds growing inside of tank berm. Erosion rill running into tank berm from cutslope.			
Corrective Action:	Maintain tank berming cutslope wall and base.			Date:

Venting:

Yes/No	
Comment:	
Corrective Action:	Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 228507 Type: WELL API Number: 103-05377 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Last recorded production January 2019. No MIT in COGCC records.
Pump jack idle at time of inspection.

Corrective Action: Well must be either:
1) Per COGCC Rule 326.b.(1) a successful mechanical integrity test shall be performed on each shut-in well within two (2) years of the initial shut-in date or
2) Be properly plugged and abandoned . Shut-in and temporarily abandoned wells must be properly reported on COGCC Form 7, Operator's Monthly Production Report.

Date: 02/04/2021

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402946522	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5654014
701102619	Inspection 701102618 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5654009