

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BARRETT-66S96W /36SESW

Location ID: 334947



Photo #5893 from entrance to location.



Photo #5894 Vent pipe open on tank open ended.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BARRETT-66S96W /36SESW

Location ID: 334947



Photo #5895 Location lacks stabilization.



Photo #5232 From inspection #699803788 conducted on 11/23/21.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BARRETT-66S96W /36SESW

Location ID: 334947



Photo #5896 Location lacks stabilization.



Photo #5232 From inspection #699803788 conducted on 11/23/21.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC BARRETT-66S96W /36SESW

Location ID: 334947



Photo #5897 Insufficient tracking BMP at entrance to location..