

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/01/2022

Submitted Date:

02/04/2022

Document Number:

691201552**FIELD INSPECTION FORM**Loc ID 481526 Inspector Name: Graber, Candice (Nikki) On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1675 BROADWAY, STE 2800

City: DENVER State: CO Zip: 80202

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

4 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, KPK		cogcc@kpk.com	<a href="#">All Inspections</a>
Gorka, Ray		RGorka@kpk.com	<a href="#">KPK environmental</a>
MacLaren, Joe		joe.maclaren@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
478617	SPILL OR RELEASE	CL	07/19/2021		-	Jillson 'A' #1	EI
481527	SPILL OR RELEASE	AC	02/03/2022		-	Jilison 2A	EI

**General Comment:**

On February 1, 2022, a COGCC third party contractor conducted a routine inspection of the Jillison 1A Facility at the request of COGCC environmental staff. During the inspection an active release was discovered adjacent to the separator. Operator environmental contractors were contacted upon spill discovery.

Inspector remained on location until an Operator crew arrived on location, controlled the release, and performed initial spill clean-up (hydrovac).

Photos attached to document site conditions.

Inspected Facilities							
Facility ID:	478617	Type:	SPILL OR	API Number:	-	Status: CL	Insp. Status: EI
Facility ID:	481527	Type:	SPILL OR	API Number:	-	Status: AC	Insp. Status: EI

**Environmental****Spills/Releases:**

Type of Spill: OIL

Estimated Spill Volume: \_\_\_\_\_

Comment: Active leak observed at separator. At the time of inspection oil was observed bubbling up out of the ground and was pooled at the surface. COGCC immediately notified KPK environmental contractors after discovery of the spill. Inspector observed initial spill response and initial spill clean-up (hydrovac). Operator submitted Form 19 Document No. 402944363 on 2/2/2022.

Corrective Action: In accordance with 913.d.(1) Operator will investigate impacts to soil, Groundwater, and surface water as soon as the impacts are discovered. Per Rule 912.b.(3) Operator will submit a Supplemental Form 19 within 10 days of spill discovery (2/11/2022).

Date: 02/11/2022

Reportable: \_\_\_\_\_

GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_

Depth to Ground Water: \_\_\_\_\_

**Water Well Complaint:**

Lat \_\_\_\_\_ Long \_\_\_\_\_

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_ Comment: \_\_\_\_\_

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402947462	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5654951">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5654951</a>
691201556	Photo Log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5654949">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5654949</a>
691201557	Spill Video	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5654950">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5654950</a>