

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/02/2022

Submitted Date:

02/02/2022

Document Number:

700703819**FIELD INSPECTION FORM**

Loc ID 335543 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10447Name of Operator: URSA OPERATING COMPANY LLCAddress: 950 17TH STREET, SUITE 1900City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**13 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, TEP	970-285-9377	COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
292194	WELL	PR	01/17/2012	GW	045-14634	LEFT HAND FED CA A4	PR
422405	WELL	PR	10/03/2011	GW	045-20571	LEFT HAND FED CA A9	PR
422408	WELL	PR	11/15/2011	GW	045-20572	LEFT HAND FED CA A3	PR
422425	WELL	PR	08/21/2011	GW	045-20577	LEFT HAND FED CA A10	PR
422456	WELL	PR	10/06/2011	GW	045-20581	LEFT HAND FED CA A2	PR

General Comment:**COGCC Inspection Report Summary**

On Wednesday 2/2/2022 at approximately 1200, I, Inspector Scott Ramsey, conducted a routine inspection at TEP Left Hand Federal A, at Location # 335543 in Garfield county Colorado.

While there, I observed normal production operations. All meters have been calibrated on location within the past year. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management. Operator (TERRA) has provided there Piceance Basin Storm water Manual of BMP's (SC-4) for a tracking pad.

Location is snow covered in areas at the time of inspection and Plowed.

During this inspection the following possible compliance issues were observed:

1. Separator units include attached storage tanks. The sight glass located on the side of the unit indicates the storage tank is full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.
2. Load lines missing bull plugs/caps
3. Well head leaking
4. Well head cellars are partially covered still open for wildlife to fall into.

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒

Signs/Marker:			
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the unit indicates the storage tank is full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	Load lines missing bull plugs/caps		
Corrective Action:	Comply with rule 603.i.	Date:	03/18/2022
Type	OTHER		
Comment:	Well head cellars are partially covered still open for wildlife to fall into.		
Corrective Action:	eliminate possibility of wildlife/personel entering cellars	Date:	02/18/2022
Type	OTHER		
Comment:	Well head leaking		
Corrective Action:	Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition	Date:	02/11/2022

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Equipment:				corrective date
Type: Emission Control Device	# 1			
Comment:				
Corrective Action:				Date:
Type: Bradenhead	# 5			
Comment:				
Corrective Action:				Date:
Type: Plunger Lift	# 5			
Comment:				
Corrective Action:				Date:
Type: Horizontal Heated Separator	# 6			
Comment:				
Corrective Action:				Date:
Type: Bird Protectors	# 7			
Comment:				
Corrective Action:				Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	300 BBLS	HEATED STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficent	Base Sufficient	Adequate		
Comment:						
Corrective Action:					Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	2	300 BBLS	HEATED STEEL AST		,	
Comment:	1 tank is not heated					
Corrective Action:						

Paint

Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities									
Facility ID:	292194	Type:	WELL	API Number:	045-14634	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	422405	Type:	WELL	API Number:	045-20571	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	422408	Type:	WELL	API Number:	045-20572	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	422425	Type:	WELL	API Number:	045-20577	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	422456	Type:	WELL	API Number:	045-20581	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Limited storm water inspection due to snow coverCorrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402947317	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5654835
700703822	Photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5654831