

**FORM  
INSP**Rev  
X/20

# State of Colorado

## Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

02/09/2022

Submitted Date:

02/11/2022

Document Number:

693200987

**FIELD INSPECTION FORM**
 Loc ID 312424 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num:
**Operator Information:**

OGCC Operator Number: 53255

Name of Operator: MARALEX RESOURCES INC

Address: P O BOX 338

City: IGNACIO State: CO Zip: 81137

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

6 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**
**Contact Information:**

Contact Name	Phone	Email	Comment
O'Hare, Mickey		amohare@maralexinc.com	
Graves, Jim	(970) 858-8550	mrinc20@qwestoffice.net	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	Engineering Integrity Supervisor

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
221569	WELL	TA	07/28/2021	GW	077-08171	FEDERAL 29-2	PA

**General Comment:**

Engineering Integrity Inspection performed on February 9, 2022. In response to Form 44 Document number 402912242.

Flowline Abandonment

**Location**Overall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Gathering Line

#

Comment: Gas gathering riser on location, will need to be removed

Corrective Action:

Date:

Type: Gas Meter Run

# 1

Comment: Gas meter, Building and riser will need to be removed before final reclamation can be passed

Corrective Action:

Date:

**Venting:**

Yes/No

Comment:

Corrective Action:

Date:

**Flaring:**

Type

Comment:

Corrective Action:

Date:

**Inspected Facilities**Facility ID: 221569 Type: WELL API Number: 077-08171 Status: TA Insp. Status: PA**Producing Well**Comment: Well was plugged and abandoned at time of inspection  
Casing is cut 4' below grade and wellhead marker welded on casingCorrective Action:  Date: **Flowline**

#1 Type: Well Site

3 of Lines

Flowline DescriptionFlowline Type: Well SiteSize: 2"Material: Carbon SteelVariance: NoAge: 10-15 YrsContents: MultiphaseIntegrity Summary

Failures:

Spills:

Repairs Made:

Coatings:

H2S:

Cathodic Protection:

Pressure Testing

Witnessed:

Test Result:

Charted:

COGCC Rules(check all that apply)☐ 1101. Installation and Reclamation☐ 1102. Operations, Maintenance, and Repair☒ 1103. AbandonmentComment: On-location flowlines dug up and removed from locationCorrective Action:  Date: **Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693200988	Photo Log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5662103">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5662103</a>