

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402955266

Date Received:

02/14/2022

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10766

Name of Operator: ARKOMA OPERATIONS LLC

Address: 2121 S COLUMBIA AVE SUITE 101

City: TULSA State: OK Zip: 74114

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Price, Andrew

918-260-8324

aprice@arkomaops.com

Recipient, Single

Inspections@catamountep.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 693903910

Inspection Date: 11/30/2021

FIR Submit Date: 12/01/2021

FIR Status: _____

Inspected Operator Information:

Company Name: CATAMOUNT ENERGY PARTNERS LLC

Company Number: 10464

Address: 1001 17TH STREET STE 1160

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 325156

Location Name: FORD-OLSON UNIT-N33N8W Number: 9SESE County: LA PLATA

Qtrqtr: SESE Sec: 9 Twp: 33N Range: 8W Meridian: N

Latitude: 37.115040 Longitude: -107.718350

FACILITY - API Number: 05-067-00 Facility ID: 214148

Facility Name: FORD-OLSON UNIT Number: 1

Qtrqtr: SESE Sec: 9 Twp: 33N Range: 8W Meridian: N

Latitude: 37.115040 Longitude: -107.718350

CORRECTIVE ACTIONS:

1 CA# 158252

Corrective Action: -Stormwater BMPs need maintenance/repair throughout the project area. Erosion (ie: seeding/mulching, erosion control blankets, etc.) and stormwater controls (BMPs) need to be installed on the well pad cut-slope as wattles are not adequate BMPs here. Controls need to be selected, sized, installed, and maintained according to good engineering practices such as those described by CDOT in their erosion control manuals. Corrective action date: 12/30/2021.

Date: 12/30/2021

Response: CA COMPLETED

Date of Completion: 02/10/2022

Wattles have been dug in, slope have been contoured and hydroseeded and erosional channel was rip rapped.

Operator
Comment:

COGCC Decision:

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Wattles have been dug in, slope have been contoured and hydroseeded and erosional channel was rip rapped.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jaime Pugh

Signed:

Title: Engineering Analyst

Date: 2/14/2022 8:04:49 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

402955276	Ford-Olson Unit 1 FIRR Resolution 2-2022
-----------	--

Total Attach: 1 Files