

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC AMERICAN SODA-67S96W /2NWNE

Location ID: 324178



Photo #5908 from entrance to location.



Photo #5909 from entrance to location.



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC AMERICAN SODA-67S96W /2NWNE

Location ID: 324178



**Photo #5910 Vent pipe on tank open ended.**



**Photo #5911 Rill erosion occurring in ditch.**



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC AMERICAN SODA-67S96W /2NWNE

Location ID: 324178



**Photo #5432 from Inspection #699803892 conducted on 12/20/21.**



**Photo #5913 Rill erosion occurring on berm.**



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC AMERICAN SODA-67S96W /2NWNE

Location ID: 324178



Photo #5433 from Inspection #699803892 conducted on 12/20/21.



Photo #5914 Insufficient velocity checks.



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC AMERICAN SODA-67S96W /2NWNE

Location ID: 324178



Photo #5434 from Inspection #699803892 conducted on 12/20/21.



Photo #5915 Location lacks stabilization.



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC AMERICAN SODA-67S96W /2NWNE

Location ID: 324178



Photo #5916 Location lacks stabilization.



Photo #5917 Insufficient tracking BMP located at entrance to location.