

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/04/2022

Submitted Date:

02/14/2022

Document Number:

701102660

**FIELD INSPECTION FORM**Loc ID 312662 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 53255

Name of Operator: MARALEX RESOURCES INC

Address: P O BOX 338

City: IGNACIO State: CO Zip: 81137

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

10 Number of Comments

6 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Graves, Jim		mrinc20@maralexinc.com	
Hahn, Travis		thahn@maralexinc.com	All Inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
222107	WELL	SI	11/01/2014	GW	077-08709	SULFUR GULCH 9-98-2 1	SI

**General Comment:**

COGCC Follow Up Inspection Report Summary

Follow up to 11/02/2020) inspection # 699802034

Uncorrected action items

- Tank label and placards are weathered and not legible.
- Tank by wellhead is not properly labeled.
- Well last produced October 2014. Last MIT performed on 11/13/2013 refer to document #2450053. MIT required.
- Vegetation growing on tank containment berm.

During this inspection the following compliance issues were observed:

- Road is not maintained
- No well sign.
- Weeds around location at well, production equipment and tank battery.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

Location			
<b>Lease Road:</b>			
Type	Access		
comment:	Road is not maintained		
Corrective Action	L Maintain road.		Date: 03/16/2022
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	No well sign.		
Corrective Action:	Install sign to comply with Rule 605.d.		Date: 05/16/2022
Type	TANK LABELS/PLACARDS		
Comment:	Tank label and placards are weathered and not legible.		
Corrective Action:	Operators shall maintain signs in a legible condition, and shall replace damaged signs. Replace tank label and placards.		Date: 03/03/2020
Type	CONTAINERS		
Comment:	Tank by wellhead is not properly labeled.		
Corrective Action:	Containers that are used to store, treat, or otherwise handle a hazardous material are required to be marked and placarded. Properly label tank.		Date: 03/03/2020
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	911		
Corrective Action:			Date: _____
<b>Good Housekeeping:</b>			
Type	WEEDS		
Comment:	Weeds around location at well, production equipment and tank battery.		
Corrective Action:	Comply with Rule 606		Date: 03/04/2022
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment: _____			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	PUMP JACK		
Comment:			
Corrective Action:			Date:
<b>Equipment:</b>			
Type: Gas Meter Run	# 1		corrective date

Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	300 BBLs	STEEL AST		,	
Comment:						
Corrective Action:						Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	
Comment:	<a href="#">Weeds in berm. See housekeeping</a>			
Corrective Action:				
		Date:		

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			
		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:			
		Date:	

**Inspected Facilities**Facility ID: 222107 Type: WELL API Number: 077-08709 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: \_\_\_\_\_Comment: Well last produced October 2014. Last MIT performed on 11/13/2013 refer to document #2450053. MIT required.

Corrective Action: Well is overdue for Mechanical Integrity Test. Perfrom MIT on well. Date: 01/31/2020 Date: 01/31/2020

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701102661	Inspection 701102660 photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5664024">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5664024</a>