

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/04/2022

Submitted Date:

02/14/2022

Document Number:

701102662

FIELD INSPECTION FORM

Loc ID 312548 Inspector Name: LONGWORTH, MIKE On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 53255
Name of Operator: MARALEX RESOURCES INC
Address: P O BOX 338
City: IGNACIO State: CO Zip: 81137

Findings:

- 9 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|-------|------------------------|---------------------------------|
| Hahn, Travis | | thahn@maralexinc.com | All Inspections |
| Graves, Jim | | mrinc20@maralexinc.com | |
| Byers, Jim | | jbyers@blm.gov | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 221891 | WELL | PR | 03/01/2021 | GW | 077-08493 | USA 1-18 JC | PR |

General Comment:

[COGCC Follow Up Inspection Report Summary](#)
Follow up to 07/29/2020 inspection # 699801528
Uncorrected action items

- Battery sign is weathered and not legible.
- Tank capacity, contents and NFPA label weathered and not legible.
- Weeds around location at well, production equipment, tank battery, inside of pit.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

| Location | | | |
|--|---|--------|-------------|
| Lease Road: | | | |
| Type | Access | | |
| comment: | Snow packed | | |
| Corrective Action: | | Date: | |
| Overall Good: <input type="checkbox"/> | | | |
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | BATTERY | | |
| Comment: | Battery sign is weathered and not legible. | | |
| Corrective Action: | Install sign to comply with Rule 605.h. | Date: | 07/27/2020 |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | Tank capacity, contents and NFPA label weathered and not legible. | | |
| Corrective Action: | Install sign to comply with Rule 605.h. | Date: | 07/27/2020 |
| Emergency Contact Number: | | | |
| Comment: | 911 | | |
| Corrective Action: | | | Date: _____ |
| Good Housekeeping: | | | |
| Type | WEEDS | | |
| Comment: | Weeds around location at well, production equipment, tank battery, inside of pit. | | |
| Corrective Action: | Comply with Rule 606 | Date: | 03/04/2022 |
| Overall Good: <input type="checkbox"/> | | | |
| Spills: | | | |
| Type | Area | Volume | |
| In Containment: No | | | |
| Comment: | | | |
| <input type="checkbox"/> Multiple Spills and Releases? | | | |
| Fencing/: | | | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | PIT | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | TANK BATTERY | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| | | | |
|--------------------------|-----|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Bird Protectors | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Gas Meter Run | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Vertical Separator | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Bradenhead | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|--------|
| PRODUCED WATER | 1 | 300 BBLs | STEEL AST | | , |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|--------------------------------------|---------------------|---------------------|-------------|
| Earth | | | | |
| Comment: | Weeds in tank berm. See housekeeping | | | |
| Corrective Action: | | | | Date: |

Venting:

| | | |
|--------------------|----|-------|
| Yes/No | NO | |
| Comment: | | |
| Corrective Action: | | Date: |

Flaring:

| | |
|--------------------|-------|
| Type | |
| Comment: | |
| Corrective Action: | Date: |

Inspected Facilities

Facility ID: 221891 Type: WELL API Number: 077-08493 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing well](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | | | | | |

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type: Blowdown Lined: NO Pit ID: Lat: Long:

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: Liner Condition:

Comment:

Corrective Action

Date:

Fencing:

Fencing Type: Fencing Condition: Adequate

Comment:

Corrective Action

Date:

Netting:

Netting Type: Netting Condition:

Comment:

Corrective Action

Date:

Anchor Trench Present: Oil Accumulation: NO 2+ feet Freeboard: YES

Comment:

Corrective Action

Date:

Type: Lined: NO Pit ID: Lat: Long:

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: Liner Condition:

Comment:

Corrective Action

Date:

Fencing:

Fencing Type: Netting/Fence com Fencing Condition: Adequate

Comment:

Corrective Action

Date:

Netting:

Netting Type: Mesh Netting Condition: _____

| | | |
|------------------------|-----------------------------|-------------------------------|
| Comment: | | Date: |
| Corrective Action | | |
| Anchor Trench Present: | Oil Accumulation: <u>NO</u> | 2+ feet Freeboard: <u>YES</u> |
| Comment: | | Date: |
| Corrective Action | | |

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|--------------------------------|---|
| 701102663 | Inspection 701102662 photo log | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5664025 |