

Inspection Photos
Operator: Logos Operating
API: 067-05363
Date: 2/11/2022



Photo 1. View of project area from the northwestern corner of the working area facing center.



Photo 2. View of the western project area from the northwestern corner facing southward. Revegetation is progressing with smooth brome, crested wheatgrass, and western wheatgrass.



Photo 3. View of area in the northwestern project area where concentrated stormwater flows off of the working area. Erosional channeling and sedimentation observed on the working pad surface and flowing into wattles full of sediment and not longer functioning.



Photo 4. View of sediment filled wattles in the northwestern project area, downstream from Photo 3.



Photo 5. View of reference area comprised of pinyon and juniper/sagebrush shrubland mosaic with Indian ricegrass, squirreltail, blue grama, and snakeweed in the understory.