

Inspection Photos  
Operator: Epic Energy  
API: 067-05367  
Date: 2/11/2022



Photo 1. View of project area from the well pad entrance facing center.



Photo 2. View of the western project area from the northwestern corner facing southward. Revegetation is sparse.



Photo 3. View of the eastern cut-slope. Rilling observed in several areas, up to approx. 10 inches deep. Little desirable vegetation observed. Bare soils are eroding. Russian thistle debris present.



Photo 4. View of waste observed on the well pad needs to be properly disposed of.



Photo 5. View of erosional channeling approx 2ft wide and deep in the northwestern project area. Cobble BMP is not adequate and no longer functioning as it is full of sediment.



Photo 6. View of reference area comprised of pinyon and juniper/sagebrush shrubland mosaic with Indian ricegrass, squirreltail, blue grama, and snakeweed in the understory.