

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/07/2022

Submitted Date:

02/08/2022

Document Number:

700703846

FIELD INSPECTION FORM

 Loc ID 335359 Inspector Name: Ramsey, Scott On-Site Inspection 2A Doc Num:

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

 OGCC Operator Number: 10456
 Name of Operator: CAERUS PICEANCE LLC
 Address: 1001 17TH STREET #1600
 City: DENVER State: CO Zip: 80202

Findings:

- 14 Number of Comments
 3 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
 PREVIOUS INSPECTIONS THAT HAVE NOT
 BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerus oilandgas.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
257648	WELL	SI	11/01/2020	GW	045-07583	KELL 35-3	SI
257649	WELL	SI	11/01/2020	GW	045-07584	GMU 26-14 (C35)	SI
257660	WELL	PR	10/13/2004	GW	045-07585	BENZEL 35-7 (C35)	PR
257665	WELL	PR	10/13/2004	GW	045-07589	KELL 35-6 (C35)	PR
273777	WELL	PR	03/05/2005	GW	045-10283	CRAIG 35-6A (C35)	PR
273779	WELL	PR	03/04/2005	GW	045-10284	CRAIG 35-5A (C35)	PR
274937	WELL	PR	03/22/2005	GW	045-13440	GMU 35-4A1(C35)	PR

General Comment:

COGCC Inspection Report Summary

On Monday 2/7/2022 at approximately 1000, I, Inspector Scott Ramsey, conducted a follow up inspection at Caerus C35, at Location # 335359 in Garfield county Colorado.

While there, I observed normal production operations. All meters have been calibrated on location within the past year. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management Area. Operator (Caerus) has provided documentation of their Best Management Practices for Sediment Tracking Controls.

C/A (Tracking controls) from document # 700702323 has been completed.

Location and access road snow covered. Plowed.

During this inspection the following compliance issues were observed:

1. Separator unit include attached storage tank. The sight glass located on the side of the unit indicates the storage tank is full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.
2. Lack of battery signage.
3. Load line missing bull plugs/caps
4. Storage of vehicles on location.

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location			
Lease Road:			
Type	Access		
comment:			
Corrective Action			Date:
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	BATTERY		
Comment:	Lack of battery signage.		
Corrective Action:	Comply with rule 605.e		Date: 05/13/2022
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	OTHER		
Comment:	Separator unit include attached storage tank. The sight glass located on the side of the unit indicates the storage tank is full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	911		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	STORAGE OF SUPL		
Comment:	Storage of vehicles on location.		
Corrective Action:	Remove vehicles or provide sundry for storage of vehicles on location		Date: 04/01/2022
Type	OTHER		
Comment:	Load line missing bull plugs/caps		
Corrective Action:	Comply with rule 603.i.		Date: 03/08/2022
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Equipment:			
Type: Plunger Lift	# 7		corrective date
Comment:			

Corrective Action:		Date:	
Type: Bradenhead	# 7		
Comment:			
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 3		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 5		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 4		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
GLYCOL	1	1000 GAL	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	500 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate

Comment:							
Corrective Action:						Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS		
CONDENSATE	1	300 BBLs	STEEL AST		,		
Comment:							
Corrective Action:						Date:	
Paint							
Condition	Adequate						
Other (Content)							
Other (Capacity)							
Other (Type)							
Berms							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate			
Comment:							
Corrective Action:						Date:	
Venting:							
Yes/No	NO						
Comment:							
Corrective Action:						Date:	
Flaring:							
Type							
Comment:							
Corrective Action:						Date:	

Inspected Facilities				
Facility ID: <u>257648</u>	Type: <u>WELL</u>	API Number: <u>045-07583</u>	Status: <u>SI</u>	Insp. Status: <u>SI</u>
Idle Well				
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____				
Comment: <u>Last produced 10/2020</u>				
Corrective Action: _____				Date: _____
Facility ID: <u>257649</u>	Type: <u>WELL</u>	API Number: <u>045-07584</u>	Status: <u>SI</u>	Insp. Status: <u>SI</u>
Idle Well				
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____				
Comment: <u>Last produced 10/2020</u>				
Corrective Action: _____				Date: _____
Facility ID: <u>257660</u>	Type: <u>WELL</u>	API Number: <u>045-07585</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Producing Well				
Comment: <u>Producing</u>				
Corrective Action: _____				Date: _____
Facility ID: <u>257665</u>	Type: <u>WELL</u>	API Number: <u>045-07589</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Producing Well				
Comment: <u>Producing</u>				
Corrective Action: _____				Date: _____
Facility ID: <u>273777</u>	Type: <u>WELL</u>	API Number: <u>045-10283</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Producing Well				
Comment: <u>Producing</u>				
Corrective Action: _____				Date: _____
Facility ID: <u>273779</u>	Type: <u>WELL</u>	API Number: <u>045-10284</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Producing Well				
Comment: <u>Producing</u>				
Corrective Action: _____				Date: _____
Facility ID: <u>274937</u>	Type: <u>WELL</u>	API Number: <u>045-13440</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Producing Well				
Comment: <u>Producing</u>				
Corrective Action: _____				Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Limited storm water inspection due to snow cover

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402950705	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5658602
700703852	Photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5658596