

# Inspection Photos

API: 017-07778

Operator: INVESTMENT EQUIPMENT LLC

Inspection Date: 2/10/2022



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 017-07778 | Date: 2/10/2022

## Inspection Photos



**Photo 1.** Facing toward the associated tank battery located 650 ft. north of the wellsite. The fence around the tank battery is not maintained and the earthen berms are not adequately sized to contain a spill.



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 017-07778 | Date: 2/10/2022

## Inspection Photos



**Photo 2.** Facing toward the associated tank battery located 650 ft. north of the wellsite. The fence around the tank battery is not maintained and the earthen berms are not adequately sized to contain a spill.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 017-07778 | Date: 2/10/2022

## Inspection Photos



**Photo 3.** Facing toward the well. Sign is posted at the pumpjack.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 017-07778 | Date: 2/10/2022

## Inspection Photos



**Photo 4.** There is a panel laying on the ground which needs to be removed or installed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 017-07778 | Date: 2/10/2022