

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/10/2022

Submitted Date:

02/15/2022

Document Number:

700703870

FIELD INSPECTION FORM

Loc ID 335158 Inspector Name: Ramsey, Scott On-Site Inspection 2A Doc Num: _____

Status Summary:

THIS IS A FOLLOW UP INSPECTION

FOLLOW UP INSPECTION REQUIRED

NO FOLLOW UP INSPECTION REQUIRED

Findings:

20 Number of Comments

5 Number of Corrective Actions

Corrective Action Response Requested

Operator Information:

OGCC Operator Number: 10531

Name of Operator: GRIZZLY OPERATING LLC

Address: 5847 SAN FELIPE #3000

City: HOUSTON State: TX Zip: 77057

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, TEP	970-285-9377	COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
293142	WELL	PR	05/08/2008	GW	045-14908	SNYDER 24A-26-692	PR
293162	WELL	PR	04/26/2008	GW	045-14910	SNYDER 34A-26-692	PR
293163	WELL	PR	05/08/2008	GW	045-14911	SNYDER 24B-26-692	PR
293164	WELL	PR	04/26/2008	GW	045-14912	SNYDER 34B-26-692	PR
293165	WELL	PR	04/23/2008	GW	045-14913	SNYDER 24C-26-692	PR
293166	WELL	PR	05/03/2008	GW	045-14914	SNYDER 34C-26-692	PR
293167	WELL	PR	04/29/2008	GW	045-14915	SNYDER 24D-26-692	PR
293168	WELL	PR	05/07/2008	GW	045-14916	SNYDER 34D-26-692	PR

General Comment:

COGCC Inspection Report Summary
On Thursday 2/10/2022 at approximately 1200, I, Inspector Scott Ramsey, conducted a routine inspection at TEP Snyder, at Location # 335158 in Garfield county Colorado.

While there, I observed normal production operations. All meters have been calibrated on location within the past year. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management. Operator (TERRA) has provided there Piceance Basin Storm water Manual of BMP's (SC-4) for a tracking pad. Location is snow covered in areas at the time of inspection and plowed.

During this inspection the following possible compliance issues were observed:

1. Storage of equipment (ECD)
2. 500 gallon tank at wells containment is full.
3. Random debris
4. Cut slope shows signs of erosion (riling) and lack of stabilization. Cut slope has waddles to help prevent run on (failing)
5. Staining

Refer to photograph of observed compliance issue.
A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location			
Lease Road:			
Type	Access		
comment:	snow covered/plowed		
Corrective Action		Date:	
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. The sight glass located on the side of the unit indicates the storage tank is full of fluid. Labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	911		
Corrective Action:		Date:	
Good Housekeeping:			
Type	STORAGE OF SUPL		
Comment:	Storage of equipment (ECD)		
Corrective Action:	Remove stored equipment	Date:	04/15/2022
Type	OTHER		
Comment:	Staining near knock out bottle at tank burner		
Corrective Action:	Remove stained material	Date:	02/25/2022
Type	OTHER		
Comment:	500 gallon tank containment is full. Tank is at well heads.		
Corrective Action:	Provide sufficient containment space to contain possible spill	Date:	02/25/2022
Type	DEBRIS		
Comment:	Random debris		
Corrective Action:	Remove debris	Date:	02/25/2022
Overall Good: <input type="checkbox"/>			

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:				
Type	WELLHEAD			
Comment:				
Corrective Action:				Date:
Type	SEPARATOR			
Comment:				
Corrective Action:				Date:

Equipment:				corrective date
Type: Plunger Lift	# 8			
Comment:				
Corrective Action:				Date:
Type: Emission Control Device	# 1			
Comment:	See stored equipment			
Corrective Action:				Date:
Type: Horizontal Heated Separator	# 8			
Comment:				
Corrective Action:				Date:
Type: Bird Protectors	# 9			
Comment:				
Corrective Action:				Date:
Type: Bradenhead	# 8			
Comment:				
Corrective Action:				Date:
Type: Ancillary equipment	# 3			
Comment:	2 chemical tanks in plastic containment and 1 500 gallon produced water tank in plastic containment see housekeeping			
Corrective Action:				Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	HEATED STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	

Other (Capacity) 375 BBL	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	4	OTHER	HEATED STEEL AST		,	
Comment: 1 tank is not heated						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity) 375 BBL		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:


Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities									
Facility ID:	293142	Type:	WELL	API Number:	045-14908	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	293162	Type:	WELL	API Number:	045-14910	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	293163	Type:	WELL	API Number:	045-14911	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	293164	Type:	WELL	API Number:	045-14912	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	293165	Type:	WELL	API Number:	045-14913	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	293166	Type:	WELL	API Number:	045-14914	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	293167	Type:	WELL	API Number:	045-14915	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	293168	Type:	WELL	API Number:	045-14916	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				



Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [Limited storm water inspection due to snow cover](#)
[1. Cut slope shows signs of erosion \(riling\) and lack of stabilization. Cut slope has waddles to help prevent run on \(failing\)](#)

Corrective Action: [Install or repair required BMPs](#)

Date: 04/15/2022

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700703875	Photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5665403