

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/15/2022

Submitted Date:

02/16/2022

Document Number:

690102854

FIELD INSPECTION FORM

Loc ID 321259 Inspector Name: Maclaren, Joe On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 39560
Name of Operator: TOP OPERATING COMPANY
Address: 3609 S WADSWORTH BLVD STE 340
City: LAKEWOOD State: CO Zip: 80235

Findings:

- 3 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Canfield, Chris		chris.canfield@state.co.us	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
HERRING, PAUL		paul.herring@topoperating.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
206541	WELL	PR	09/15/2021	GW	013-06036	TANAKA BROS 1	PA

General Comment:

[COGCC Engineering Integrity Inspection; Flowline Inspection](#)
[Photos uploaded](#)

Inspected Facilities

Facility ID: 206541 Type: WELL API Number: 013-06036 Status: PR Insp. Status: PA

Flowline

#1	Type: Well Site	of Lines	
----	-----------------	----------	--

Flowline Description

Flowline Type: Well Site Size: 2" Material: Carbon Steel
 Variance: _____ Age: _____ Contents: _____

Integrity Summary

Failures: _____ Spills: _____ Repairs Made: _____
 Coatings: _____ H2S: _____ Cathodic Protection: _____

Pressure Testing

Witnessed: _____ Test Result: _____ Charted: _____

COGCC Rules (check all that apply)

1101. Installation and Reclamation 1102. Operations, Maintenance, and Repair 1103. Abandonment

Comment: COGCC inspector met with Top contract personnel on location (Amen Oilfield); crews were in the process of removing historically impacted soils/ groundwater and production equipment from location. An open excavation at the PA well exposed flowlines; (2) 1" poly and (1) 2" CS flowline cut ends were observed E-W walls of the excavation. The Tanaka Bros #1 well has been plugged and abandoned; COGCC form 42 notice of start of plugging operations doc #402881829 was received on 11/29/2021. The facility is being decommissioned; tanks/ equipment are being removed. The on location flowlines are scheduled to be removed (wellhead, gas supply, dump/ process lines). COGCC form 42 flowline pre-abandonment 30 day notice doc #402860828 was received 11/03/2021. Also, (1) off location domestic tap flowline (1" yellow poly line) was observed exposed in the wellhead excavation. Per conversation with the contract lead, this flowline is scheduled to be abandoned in place. The flowline runs approximately 400' southwest to a large agricultural/ equipment building. The riser and tie in at the building has been isolated/ removed and buried below grade (confirmed via inspection w/ Amen personnel). Excavation and remediation work is in progress.

Note: COGCC rule 1101.C (4) Within 30 days of realigning, abandoning, discovering, or receiving notification that a registered domestic tap has been re-aligned or abandoned, the operator must report the change to the Director by submitting a Flowline Report, Form 44.

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
As outlined on COGCC form 19 spill report Doc #402954776 received on 02/11/2022: Historic impacted soil was observed during wellhead closure sampling activities. The well has been P&A and cut and capped.	maclarej	02/16/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690102855	Excavation at WH; flowlines exposed (GW removal)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5666588
690102856	Facility dump/ process FL risers (to be removed)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5666589
690102857	Equipment removed	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5666590

690102858	Domestic tap; riser removed at service tie in	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5666591
-----------	---	---