

Inspection Photos  
Operator: Arkoma  
API: 067-05373  
Date: 2/15/2022



Photo 1. View of project area from the well pad entrance facing center. Well pad surface is not stabilized.



Photo 2. View of the northern project area from the northeastern corner facing westward. Revegetation is progressing with smooth brome, crested wheatgrass, rubber rabbitbrush, and western wheatgrass.



Photo 3. View of rutting up to approx 10-12inches deep on the well pad needing stabilization.




Photo 4. View of erosional channels forming within the northern project area.



Photo 5. View of additional erosional channeling within the northern project area.



Photo 6. View of reference area comprised of sagebrush shrubland/pinyon juniper woodland mosaic comprised of blue grama, Indian ricegrass, prickly pear, and yucca in the understory.