

Inspection Photos
Operator: Arkoma
API: 067-08193
Date: 2/15/2022



Photo 1. View of project area from the well pad entrance facing center.



Photo 2. View of the northern project area from the northeastern corner facing westward. Revegetation is progressing with smooth brome, crested wheatgrass, and western wheatgrass.



Photo 3. View of stormwater BMPs in the northern project area that need maintenance.



Photo 4. View of wattle at the well pad entrance that is full of sediment and is not an adequate BMP for this location. Maintenance is needed.



Photo 5. View of reference area comprised of open grass field, largely comprised of grasses such as smooth brome, western wheatgrass, and crested wheatgrass.