

Inspection Photos  
Operator: Arkoma  
API: 067-09139  
Date: 2/15/2022



Photo 1. View of project area from the well pad entrance facing center.



Photo 2. View of the northern project area from the northeastern corner facing westward. Revegetation is progressing with smooth brome, crested wheatgrass, and western wheatgrass.





Photo 3. View of the eastern project area from the northeastern corner facing southward.



Photo 4. View of ponding observed in the northwestern well pad. A properly armored outlet is needed here.





Photo 5. View of bare soils, failed wattles, and erosional channeling occurring within the western project area.



Photo 6. Another view of bare and unstabilized soils and erosional channeling within the western project area.





Photo 7. View of reference area comprised of open grass field, largely comprised of grasses such as smooth brome, western wheatgrass, and crested wheatgrass.