

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL-67S96W /11SWNE

Location ID: 334969



Photo #5962 from entrance to location.



Photo #5965 Vent pipe on tank open ended.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL-67S96W /11SWNE

Location ID: 334969



Photo #5963 Location lacks stabilization.



Photo #5964 Insufficient tracking controls.