



Aug 19, 2021 at 11:58:54 AM
39.986384,-104.527789
Manilla Rd
Teenesburg CO 80643
United States
COGCC



Here the Crude Oil Tank is situated higher than Produced Water Tank. They are both connected to the manifold in the Separator. A failed valve in the manifold could cause a gravity flow until the tanks equalize. The wells may also still be connected and could be the source of the overtopping. Easy access from Manilla Road and 160th Ave. suggests possible tampering.



The overtopping on the produced water tank is encroaching on the secondary containment freeboard, but no longer appears to be flowing.



Spray from this loose gasket might also be an indication of tampering.

