

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/31/2022

Submitted Date:

02/17/2022

Document Number:

702200006

FIELD INSPECTION FORM

Loc ID 320083 Inspector Name: HICKEY, MIKE On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10711
 Name of Operator: PAINTED PEGASUS PETROLEUM LLC
 Address: 16820 BARKER SPRINGS RD #521
 City: HOUSTON State: TX Zip: 77084

Findings:

6 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Ferrin, Jeremy		jeremy.ferrin@state.co.us	

General Comment:

Responding to a report that a Painted Pegasus tank was over topping it was discovered that there was standing black liquid/parafin outside the produced water tank. The separator was also discharging what appeared to be orange produced water. We applied for emergency procurement to remove some of the liquid from the tank immediately and begin the process of shutting in the wells and cleaning up the mess.

Well master valve seemed seized and would not move. Ball valves on the well should have held, but may be washed out.

Wells will need to be plugged to stop the flow.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment: Fluid from the pw tank is contained. The liquid from the separator is not.

Multiple Spills and Releases?

Equipment:

Type: Horizontal Separator	# 1		corrective date
Comment: Leaking. Spraying. Some staining shows on weeds outside the perimeter fence.			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment: Oil tank not full; not leaking.				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	PBV FIBERGLASS		39.986317,-104.527897
Comment: PW Tank is full and overflowing.					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Insufficient	Adequate
Comment:				
Corrective Action:				Date:

Wells Served By Facilities Above

AirsID

API Number
001-07968
001-07978
001-07751

API Number	AirsID
------------	--------

Venting:

Yes/No	YES		
Comment:	leaking through the separator		
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

COGCC Comments

Comment	User	Date
This is an ongoing leak. The master valve seems siezed. Flow to the separator must be stopped. All 3 wells feeding this battery need to be Plugged ASAP.	hickeymi	02/17/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
702200007	P3 UPRR Pan Am E #2	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5667577
702200008	Eleanor Arnold well	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5667578
702200009	UPRR #1	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5667579
702200010	P3 UPRR Pan Am E #2 wellhead	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5667580