

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/18/2022

Submitted Date:

02/18/2022

Document Number:

699804175

FIELD INSPECTION FORM

Loc ID 335186 Inspector Name: De Paolo, Corey On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:
OGCC Operator Number: 10433
Name of Operator: LARAMIE ENERGY LLC
Address: 1001 17TH STREET #1900
City: DENVER State: CO Zip: 80202

Findings:

- 14 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|-------|---------------------------------------|---------|
| , Laramie | | cogccnotifications@laramie-energy.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------------------|-------------|
| 275532 | WELL | PR | 12/01/2019 | GW | 045-10345 | CASCADE CREEK 705-22-43 | PR |
| 283504 | WELL | PR | 05/02/2007 | GW | 045-11927 | CASCADE CREEK 797-05-06DA | PR |
| 283506 | WELL | PR | 09/10/2007 | GW | 045-11928 | CASCADE CREEK 797-05-12D | PR |
| 283581 | WELL | PR | 03/31/2008 | GW | 045-11960 | CASCADE CREEK 797-05-14DA | PR |
| 283583 | WELL | PR | 04/11/2007 | GW | 045-11961 | CASCADE CREEK 797-05-06DB | PR |

General Comment:

COGCC Inspection Report Summary
On Thursday 2/17/22 at approximately 13:30 hours, I, Inspector Corey De Paolo, Conducted an on-site inspection at LARAMIE ENERGY LLC CC /0705-22-43 Pad, Location #335186 in Garfield County Colorado.
While there, I observed normal production operations.
During this inspection the following compliance issues were observed:

1) Location lacks stabilization. Insufficient tracking BMP at entrance to location with a corrective action date of 3/4/22.

- Location is located in a high priority habitat area. All drainages contribute to Cascade creek.

A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.
This is a summary of inspection report.

Location

Overall Good:

Signs/Marker:

| | | | |
|--------------------|----------------------|-------|--|
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | BATTERY | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment:

Corrective Action:

Date:

Overall Good:

Spills:

| Type | Area | Volume | | |
|------|------|--------|--|--|
| | | | | |

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

| Type | # | Comment | Corrective Action | Date | corrective date |
|-----------------------------|-----|----------------------------------------------------------------------------------------------------------|-------------------|------|-----------------|
| Gas Meter Run | # 5 | | | | |
| | | | | | |
| | | | | | |
| Bradenhead | # 5 | No form of pressure monitoring equipment located on braden heads. All braden head valves are accessible. | | | |
| | | | | | |
| | | | | | |
| Bird Protectors | # 2 | | | | |
| | | | | | |
| | | | | | |
| Horizontal Heated Separator | # 5 | | | | |
| | | | | | |
| | | | | | |
| Plunger Lift | # 5 | All wells on plunger lift | | | |
| | | | | | |
| | | | | | |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|----------|---|----------|------|---------|--------|
| | | | | | |

| | | | | | |
|--------------------|----------|---------------------|---------------------|-------------|-------|
| CONDENSATE | 1 | 300 BBLs | STEEL AST | | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |
| Paint | | | | | |
| Condition | Adequate | | | | |
| Other (Content) | | | | | |
| Other (Capacity) | | | | | |
| Other (Type) | | | | | |
| Berms | | | | | |
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
| Metal | Adequate | Walls Sufficient | Base Sufficient | Adequate | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |
| Venting: | | | | | |
| Yes/No | NO | | | | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |
| Flaring: | | | | | |
| Type | | | | | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

| Inspected Facilities | | | | | | | | | |
|-----------------------|------------------|-------|-------------|-------------|------------------|---------|-----------|---------------|-----------|
| Facility ID: | <u>275532</u> | Type: | <u>WELL</u> | API Number: | <u>045-10345</u> | Status: | <u>PR</u> | Insp. Status: | <u>PR</u> |
| Producing Well | | | | | | | | | |
| Comment: | <u>Producing</u> | | | | | | | | |
| Corrective Action: | | | | | Date: | | | | |
| Facility ID: | <u>283504</u> | Type: | <u>WELL</u> | API Number: | <u>045-11927</u> | Status: | <u>PR</u> | Insp. Status: | <u>PR</u> |
| Producing Well | | | | | | | | | |
| Comment: | <u>Producing</u> | | | | | | | | |
| Corrective Action: | | | | | Date: | | | | |
| Facility ID: | <u>283506</u> | Type: | <u>WELL</u> | API Number: | <u>045-11928</u> | Status: | <u>PR</u> | Insp. Status: | <u>PR</u> |
| Producing Well | | | | | | | | | |
| Comment: | <u>Producing</u> | | | | | | | | |
| Corrective Action: | | | | | Date: | | | | |
| Facility ID: | <u>283581</u> | Type: | <u>WELL</u> | API Number: | <u>045-11960</u> | Status: | <u>PR</u> | Insp. Status: | <u>PR</u> |
| Producing Well | | | | | | | | | |
| Comment: | <u>Producing</u> | | | | | | | | |
| Corrective Action: | | | | | Date: | | | | |
| Facility ID: | <u>283583</u> | Type: | <u>WELL</u> | API Number: | <u>045-11961</u> | Status: | <u>PR</u> | Insp. Status: | <u>PR</u> |
| Producing Well | | | | | | | | | |
| Comment: | <u>Producing</u> | | | | | | | | |
| Corrective Action: | | | | | Date: | | | | |

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|----------------------------------------------------|
| Gravel | Fail | | | | | Gravel insufficient |
| Other | Fail | | | | | Insufficient tracking BMP at entrance to location. |
| Berms | | | | | | |
| Compaction | Fail | | | | | Location lacks stabilization |
| | | Sediment Traps | | | | |
| Sediment Traps | | | | | | |
| | | Berms | | | | |
| | | Check Dams | | | | |
| | | Culverts | | | | |
| | | Ditches | | | | |
| Ditches | | | | | | |

Comment: [Location lacks stabilization. Insufficient tracking BMP at entrance to location.](#)

Corrective Action: [Oil and gas operators shall implement and maintain Best Management Practices \(BMPs\) at all oil and gas locations](#)

Date: 03/04/2022

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

| Comment | User | Date |
|--------------------------------------------------------------|----------|------------|
| Refer to Storm water for corrective actions. | depaoloc | 02/18/2022 |

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-----------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 699804176 | Photos for Insp. #699804175 | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5668529 |