

Inspection Photos  
Location Name: Redwin 22-4  
API #069-06227




Wellhead sign




Tubing pressure

**Inspection Photos**  
**Location Name: Redwin 22-4**  
**API #069-06227**



**Casing pressure**



**Bradenhead pressure**