

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/14/2022

Submitted Date:

02/15/2022

Document Number:

696203433

FIELD INSPECTION FORMLoc ID 335542 Inspector Name: Trujillo, Aaron On-Site Inspection ☐ 2A Doc Num: ☐**Operator Information:**

OGCC Operator Number: 10447

Name of Operator: URSA OPERATING COMPANY LLC

Address: 950 17TH STREET, SUITE 1900

City: DENVER State: CO Zip: 80202

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

5 Number of Comments

3 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, TEP		COGCCInspectionReports@terraep.com	
		anna.omalley@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
335542	LOCATION	AC			-	VALLEY FARMS E PAD	RI

General Comment:

On 2/14/2022, Reclamation Specialist Trujillo conducted an interim reclamation and stormwater inspection at the Valley Farms E Pad Location in Garfield County, CO.

Inspection is a follow-up to #696203249 and #696203376 to document compliance with the following corrective actions:

- Weeds/Debris
- Stormwater

Refer to the "stormwater", "reclamation" and "good housekeeping" sections of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspections that have not been addressed are still applicable.

A follow up inspection on this site will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type	WEEDS		
Comment:	<p>Inspection #696203249 observed Undesirable plant species established on the interim areas of the Location. Inspection noted that weeds have died, will soon break off and is considered debris. Inspection required Operator to comply with Rule 606 and remove undesirable plants and weed debris.</p> <p>It was observed in this inspection that corrective actions to keep the Location free of Undesirable plant species and weed debris have not been addressed; original corrective action and date remains applicable.</p>		
Corrective Action:	Comply with rule 606 and remove undesirable plant species / weed debris.	Date:	11/06/2021

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment

Inspection #696203249 observed that the Location is not progressing towards 1003 standards. Inspection required Operator to comply with 1003 rules by 12/15/2021.

Limited visibility due to snow cover prevented Reclamation Specialist from assessing compliance with 1003 rules on the interim areas of the Location; no FIRR has been submitted stating that the CA has been addressed.

This CA will remain applicable; a followup inspection will be conducted to determine compliance with 1003 rules and the CA.

Corrective Action **Comply with 1003 Rules.**

Date **12/15/2021**

Overall Interim Reclamation **Fail**

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: _____

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Comment: Corrective Action:

Date _____

Overall Final Reclamation _____

Well Release on Active Location ☐Multi-Well Location ☐**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [See "COGCC Comments" for comments regarding stormwater](#)Corrective Action: [Comply with Rule 1002.f](#)

Date: 03/09/2021

Pits: ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
STORMWATER COMMENTS Inspection Nos. 700701946, 700702256, 696203249 and 696203376 observed that control measures to protect/stabilize the slopes of the Location are missing or insufficient. Inspections required Operator to comply with Rule 1002.f by 3/9/2021 Limited visibility due to snow cover prevented Reclamation Specialist from inspecting all areas of concern identified in the previous inspections; Operator appears to have placed erosion blankets on a portion of the slopes; however, there are areas of the cut slopes where controls measures appear to remain missing. Additionally, it does not appear that the erosion blankets were installed to the very top of the cut slopes, but rather to the base of a vertical cut; control measures to protect and stabilize the slopes appear to remain missing or inadequate. A followup inspection will need to be conducted to determine compliance with 1002.f Rules and the corrective actions once the remaining cut slopes are no longer covered in snow. Corrective action and date will remain applicable. It was also observed in this inspection that the production areas not covered with snow do not appear to be stabilized. Ensure BMPs are implemented and maintained to ensure pad remains stabilized, and to mitigate vehicle tracking.	trujilloam	02/15/2022

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
402957483	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5665510
696203434	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5665507