

Inspection Photos
Operator: Simcoe
API: 067-09054
Date: 2/18/2022



Photo 1. View of project area from the well pad entrance facing center.



Photo 2. View of the eastern project area from the northeastern corner facing southward. Revegetation appears to be progressing with intermediate wheatgrass and crested wheatgrass. Vegetation cover and weeds should be monitored and managed during the active growing season.



Photo 3. View of the northern portion of the project area from the northeastern corner facing westward. Scattered musk thistles observed through snow (inset).



Photo 4. View of fencing and culvert debris observed within the southeastern corner of the project area.



Photo 5. View of reference area vegetation comprised of open grass fields largely snow covered at this time.