

Inspection Photos
Operator: Simcoe
API: 067-07851
Date: 2/18/2022



Photo 1. View of project area from the well pad entrance facing center.



Photo 2. View of the eastern project area from the northeastern corner facing southward. Revegetation appears to be progressing with intermediate wheatgrass and crested wheatgrass, although largely snow covered. Vegetation cover and weeds should be monitored and managed during the active growing season.



Photo 3. View of the northern portion of the project area from the northeastern corner facing westward.



Photo 4. View of reference area vegetation comprised of open grass fields mixed with scattered sagebrush, rubber rabbitbrush, and pinyon and juniper trees.