

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/22/2022

Submitted Date:

02/24/2022

Document Number:

700703899**FIELD INSPECTION FORM**

Loc ID 336037	Inspector Name: Ramsey, Scott	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
Operator Information: OGCC Operator Number: <u>96850</u> Name of Operator: <u>TEP ROCKY MOUNTAIN LLC</u> Address: <u>1058 COUNTY ROAD 215</u> City: <u>PARACHUTE</u> State: <u>CO</u> Zip: <u>81635</u>				Findings: 15 Number of Comments 4 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
				ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:			
Contact Name	Phone	Email	Comment
, TEP	970-285-9377	COGCCInspectionReports@terraep.com	

Inspected Facilities:							
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
296416	WELL	PR	11/01/2021	GW	045-16013	GYPSUM RANCH B3	PR
296454	WELL	PR	11/01/2021	GW	045-16036	GYPSUM RANCH B4	PR
296457	WELL	SU	04/16/2008	GW	045-16039	GYPSUM RANCH B7	SU
296459	WELL	PR	11/01/2021	GW	045-16041	GYPSUM RANCH B9	PR
296461	WELL	PR	12/01/2021	GW	045-16043	GYPSUM RANCH B13	PR

General Comment:

COGCC Inspection Report Summary
 On Tuesday 2/22/2022 at approximately 1100, I, Inspector Scott Ramsey, conducted a routine inspection at TEP Gypsum B, at Location # 336037 in Garfield county Colorado.
 Any Corrective Actions from previous Inspections that have not been addressed are still applicable.
 While there, I observed normal production operations. All meters have been calibrated on location within the past year. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management, the internal buffer of the 411 (PWS) protection and Geologic Hazard area. Operator (TERRA) has provided there Piceance Basin Storm water Manual of BMP's (SC-4) for a tracking pad.
 Location is snow covered in areas at the time of inspection and plowed.
 During this inspection the following possible compliance issues were observed:

1. Separator units include attached storage tanks. The sight glass located on the side of the unit indicates the storage tank is full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.
2. Random debris.
3. Load lines missing plug/cap.
4. Stored equipment (ECD)
5. Unmarked risers.

Refer to photograph of observed compliance issue.
 A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.
 This is a summary of inspection report.

Location				
Lease Road:				
Type	Access			
comment:	Snow covered			
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
Type	TANK LABELS/PLACARDS			
Comment:				
Corrective Action:				Date:
Type	OTHER			
Comment:	1. Separator units include attached storage tanks. The sight glass located on the side of the unit indicates the storage tank is full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.			
Corrective Action:				Date:
Type	WELLHEAD			
Comment:				
Corrective Action:				Date:
Type	BATTERY			
Comment:				
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	911			
Corrective Action:				Date: _____
Good Housekeeping:				
Type	OTHER			
Comment:	Unmarked risers.			
Corrective Action:	Mark or remove risers			Date: 04/01/2022
Type	DEBRIS			
Comment:	Random debris			
Corrective Action:	Remove debris			Date: 03/04/2022
Type	STORAGE OF SUPL			
Comment:	Stored equipment (ECD)			
Corrective Action:	Remove stored equipment			Date: 04/01/2022
Type	OTHER			
Comment:	Load lines missing plug/cap.			
Corrective Action:	Install cap/bull plug			Date: 04/01/2022
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type WELLHEAD

Comment:

Corrective Action:

Date:

Equipment:

corrective date

Type: Plunger Lift

4

Comment:

Corrective Action:

Date:

Type: Bradenhead

4

Comment:

Corrective Action:

Date:

Type: Bird Protectors

3

Comment:

Corrective Action:

Date:

Type: Horizontal Heated Separator

4

Comment:

Corrective Action:

Date:

Type: Emission Control Device

1

Comment: [See stored equipment](#)

Corrective Action:

Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	3	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity		Permeability (Wall)		Permeability (Base)		Maintenance	
Metal	Adequate		Walls Sufficent		Base Sufficent		Adequate	
Comment:								
Corrective Action:							Date:	
Contents		#	Capacity	Type		Tank ID	SE GPS	
PRODUCED WATER		3	300 BBLS	STEEL AST			,	

Comment:		
Corrective Action:		Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 296416 Type: WELL API Number: 045-16013 Status: PR Insp. Status: PR**Producing Well**Comment: Producing

Corrective Action:

Date:

Facility ID: 296454 Type: WELL API Number: 045-16036 Status: PR Insp. Status: PR**Producing Well**Comment: Producing

Corrective Action:

Date:

Facility ID: 296457 Type: WELL API Number: 045-16039 Status: SU Insp. Status: SU**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: Last MIT done 7/27/2021

Corrective Action:

Date: _____

Facility ID: 296459 Type: WELL API Number: 045-16041 Status: PR Insp. Status: PR**Producing Well**Comment: Producing

Corrective Action:

Date:

Facility ID: 296461 Type: WELL API Number: 045-16043 Status: PR Insp. Status: PR**Producing Well**Comment: Producing

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700703906	Photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5673673