

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/24/2022

Submitted Date:

02/25/2022

Document Number:

699602799**FIELD INSPECTION FORM**Loc ID 420803 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:7 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		dnr_cogccengineering@state.co.us	
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
420801	WELL	PR	08/01/2020	OW	123-32718	ROHR A 28-25	PA

General Comment:

This is a **PLUGGED & ABANDONED WELL / CEMENTING** inspection.

Well(s): 1: Plugged & Abandoned | PA.

Plugging Operations / Cementing. Intermediate plugs, cementing.

Battery: Inactive | Shut-down.

Inactive Battery SE corner GPS coordinates: 40.450048 / -104.557089

Location**Lease Road:**

Type	Access		
comment:	Adequate		
Corrective Action:		Date:	

Overall Good: ☐**Signs/Marker:**

Type	OTHER		
Comment:	Jobsite safety signage present.		
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Plunger Lift	# 0		corrective date
Comment:	Plugged & Abandoned PA. Equipment removed.		
Corrective Action:		Date:	

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 420801 Type: WELL API Number: 123-32718 Status: PR Insp. Status: PA

CementCement ContractorContractor Name: A-Plus

Contractor Phone: _____

Surface Casing

Cement Volume (sx): _____

Circulate to Surface: _____

Cement Fall Back: _____

Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____

Good Return During Job: _____

Production Casing

Cement Volume (sx): _____

Good Return During Job: _____

Plugging OperationsDepth Plugs(feet range): 3508'-2330'Cement Volume (sx): 4 sxs

Good Return During Job: _____

Cement Type: _____

Comment:

Workover Contractor: A-Plus. Rig #12.
Cementing Contractor: A-Plus.

Reference:

Form 6N on file. Notice of Intent to Abandon date: 11/17/2021. Approved.

Form 42 on file. Notice of MIRU.

Start Date: 02/18/2021. Approved.

Form 42 on file. Notice of Plugging Operations.

Start Date: 02/18/2021. Approved.

Form 17 Bradenhead Test on file. Date: 02/22/2022. Approved.

Intermediate plugs. Cementing.

SAFETY MEETING, CHECK PSI, CSG O, SURFACE O, LOAD W/80 BBLS & TEST CSG TO 500 PSI, GOOD

TEST, RUWL, PU 4.5 11.6# CIBP GET TO SET DEPTH @3508,HAD MIS FIRE,ON THE WAY OUT HUNG UP

@1469,WORK FREE,LD TOOLS,REHEAD WIRELINE,PU 4.5 11 .6# CIBP & SET

@3508,PU 3.125

DUMPBAILER & SPOT 2 SACS CMT,PU 4.5 11.6# CIBP & SET @2330,PU 3.125

DUMPBAILER & SPOT 2

SACS CMT,PU 4.5 JET CUTTER & CUT CSG @940,RDWL,NDB OP, NU NIGHT CAP, SWI.

Corrective Action: _____

Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On THU 02/24/2022 at approximately 13:15 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: NOBLE ENERGY INC Location Name: ROHR USX A /28-25 Location ID: 420803 Well Name(s): Rohr A 28-25. API: 05-123-32718. Location County: Weld County, Colorado Weather: Sunny, wet w/ mud, snow patches from prior storm.</p> <p>While there, I observed: Well(s): 1: Plugged & Abandoned PA. Plugging Operations / Cementing. Intermediate plugs, cementing. Battery: Inactive Shut-down. Inactive Battery SE corner GPS coordinates: 40.450048 / -104.557089</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	02/25/2022

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699602801	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5674931