

**Inspection Photos**  
**Location Name: Elaine 41-18**  
**Location ID: 320103**



**Pic 1 Master valve is free moving, and in the shut position. All casing, flowlines, and bradenhead valves are in the close position prior to inspection. LOTO is installed on master valve**



**Pic 2 Midstream equipment needs to be removed.**

**Inspection Photos**  
**Location Name: Elaine 41-18**  
**Location ID: 320103**

Feb 28, 2022 at 12:31:17 PM  
39.969664,-104.586467  
COGCC



**Pic 3 verticle separators, 1 heated. Unable to access separator house due to condition of building**

Feb 28, 2022 at 12:31:30 PM  
39.969664,-104.586467  
COGCC



**Pic 4 inside of separator house**

**Inspection Photos**  
**Location Name: Elaine 41-18**  
**Location ID: 320103**

Feb 28, 2022 at 12:32:46 PM  
39.970193,-104.586458  
Adams County  
COGCC



**Pic 5 tanks, oil tank appears to be empty, water tank is almost full**

Feb 28, 2022 at 12:44:53 PM  
39.970420,-104.586428  
Adams County  
COGCC



**Fluid level in concrete buried vault is almost full.**