

Inspection Photos

Location Name: UPRR Julie 1

Location ID: 320137



Pic 1 All ball valves were in close position at time of inspection. Master valve was seized in position, unable to determine if valve is open or shut. Bradenhead needle valve is shut.



Pic 2 tank appears to be empty



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: UPRR Julie 1

Location ID: 320137



Pic 3 Separator, and abandoned midstream.