



**Location**

Overall Good:

**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:	adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type			corrective date
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 4		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 8		
Comment:			

Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	appears plumbed to surface		
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 4		
Comment:	automation		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	gas engine in pump jack house laying on it side		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLs	FIBERGLASS AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate

Comment: <a href="#">Shares containment with 1 crude tank</a>						Date:	
Corrective Action:						Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS		
PRODUCED WATER	1	<50 BBLS	PBV CONCRETE		,		
Comment:						Date:	
Corrective Action:						Date:	
<b>Paint</b>							
Condition							
Other (Content)							
Other (Capacity)							
Other (Type)							
<b>Berms</b>							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Earth	Adequate	Walls Sufficent	Base Sufficient	Adequate			
Comment: <a href="#">shares containment with 2 crude tanks</a>						Date:	
Corrective Action:						Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS		
CRUDE OIL	2	300 BBLS	STEEL AST		39.918750,-104.583070		
Comment:						Date:	
Corrective Action:						Date:	
<b>Paint</b>							
Condition	Adequate						
Other (Content)							
Other (Capacity)							
Other (Type)							
<b>Berms</b>							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Earth	Adequate	Walls Sufficent	Base Sufficient	Adequate			
Comment:						Date:	
Corrective Action:						Date:	
<b>Wells Served By Facilities Above</b>							
API Number				AirsID			
001-07301							
001-08887							
001-07950							
<b>Venting:</b>							
Yes/No	NO						
Comment:						Date:	
Corrective Action:						Date:	
<b>Flaring:</b>							

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 202545 Type: WELL API Number: 001-07950 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: SI

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 05/21/2020 Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary                      On Monday 2/28/2022 at approximately 1330 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection:                      Operator: Painted Pegasus Petroleum (3P)                      Location: Hosmer 21-32</p> <p align="center">API # 05-001-07950</p> <p align="right">County: Adams</p> <p>While there, I observed a wellsite and tank battery. SI                      Because P3 is not actively managing any of its Colorado Wells or Locations there is a direct threat to public health, safety and welfare, including the environment and wildlife resources. Therefore, the COGCC will undertake steps to, at a minimum, shut-in all of P3's wells and lock-out/tag-out P3's flow lines. COGCC may take additional actions to protect public health, safety and welfare, including the environment and wildlife resources, without providing advanced notice.</p> <p>See attached photos.</p> <p>Location: muddy, Weather: clear.</p> <p>This is a summary of the inspection report.</p>	revasr	02/28/2022

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699305100	location pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5676710">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5676710</a>