

# Inspection Photos

API: 071-06902

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 2/28/2022



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06902 | Date: 2/28/2022

## Inspection Photos



**Photo 1.** There has been rock rip/rap outlet protection installed at the culvert near the main road in Lorencito Canyon. Disturbed areas have been seeded.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06902 | Date: 2/28/2022

## Inspection Photos



**Photo 2.** Facing southwest along the main road to the well site. There area rock check dams installed along the road side and areas of erosion have been repaired.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06902 | Date: 2/28/2022

## Inspection Photos



**Photo 3.** Facing southwest along the main road to the well site. There area rock check dams installed along the road side and areas of erosion have been repaired.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06902 | Date: 2/28/2022

## Inspection Photos



**Photo 4.** Facing northeast along the access road to the well site.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06902 | Date: 2/28/2022

## Inspection Photos



**Photo 5.** Facing northeast toward the well site.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06902 | Date: 2/28/2022