

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/28/2022

Submitted Date:

03/01/2022

Document Number:

699602828**FIELD INSPECTION FORM**Loc ID 420827 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:7 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		dnr_cogccengineering@state.co.us	
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
420824	WELL	PR	11/01/2020	OW	123-32723	QC USX A32-19	PA

General Comment:

This is a **PLUGGED & ABANDONED WELL / CEMENTING** inspection.

Well(s): 1: Plugged & Abandoned | PA.

Plugging Operations / Cementing. Initial plugs, cementing.

Battery: Inactive | Shut-down.

Inactive Battery SE corner GPS coordinates: 40.449382 / -104.581106

Location**Lease Road:**

Type	Access		
comment:	Adequate		
Corrective Action:		Date:	

Overall Good: ☐**Signs/Marker:**

Type	OTHER		
Comment:	Jobsite safety signage present.		
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Plunger Lift	# 0		corrective date
Comment:	Plugged & Abandoned PA. Equipment removed.		
Corrective Action:		Date:	

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 420824 Type: WELL API Number: 123-32723 Status: PR Insp. Status: PA

CementCement ContractorContractor Name: Axis Energy

Contractor Phone: _____

Surface Casing

Cement Volume (sx): _____

Circulate to Surface: _____

Cement Fall Back: _____

Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____

Good Return During Job: _____

Production Casing

Cement Volume (sx): _____

Good Return During Job: _____

Plugging OperationsDepth Plugs(feet range): 6,648'Cement Volume (sx): Dump bail

Good Return During Job: _____

Cement Type: _____

Comment:

Workover Contractor: Axis Energy Services. Rig #714.
Cementing Contractor: Axis Energy Services.

Reference:

Form 6N on file. Notice of Intent to Abandon date: 01/20/2022. Approved.

Form 42 on file. Notice of MIRU.

Start Date: 02/28/2022. Approved.

Form 42 on file. Notice of Plugging Operations.

Start Date: 02/28/2021. Approved.

Form 17 Bradenhead Test on file. Date: 02/28/2022. Approved.

Initial plugs. Cementing.

IWP 430 PSI J 430 PSI / 5 PSI

HELD PJSM. FINISHED RU. PERFORMED FORM 17. CONTROLLED WELL BY REV

CIRC. PUMPER LET CM

KNOW THERE IS A PLUNGER CURRENTLY IN WELL, ONCE PLUNGER CAME UP,
BULLHEAD WELL ND

WH, TEST AND NU BOP_ PROBLEM UNLANDING TBG MANDREL. BROUGHT OUT

RMOR TUBING JACK

AND GOT UNLANDED @ 3,000 PSI / 125K PULL. POOH TBG, LD ALL OF IT. RUWL, RIH

& SET CIBP @

6,648", DUMP BAIL, RD WI. SECURE WELL AND SDFN.

Corrective Action: _____

Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On MON 02/28/2022 at approximately 14:29 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: NOBLE ENERGY INC Location Name: QC USX /A32-19 Location ID: 420827 Well Name(s): QC USX A32-19. API: 05-123-32723. Location County: Weld County, Colorado Weather: Sunny, wet w/ mud, snow patches from prior storm.</p> <p>While there, I observed: Well(s): 1: Plugged & Abandoned PA. Plugging Operations / Cementing. Initial plugs, cementing. Battery: Inactive Shut-down. Inactive Battery SE corner GPS coordinates: 40.449382 / -104.581106</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	03/01/2022

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699602829	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5677715