

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

03/01/2022

Submitted Date:

03/01/2022

Document Number:

699305109

FIELD INSPECTION FORM
 Loc ID 320410 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 10711

Name of Operator: PAINTED PEGASUS PETROLEUM LLC

Address: 16820 BARKER SPRINGS RD #521

City: HOUSTON State: TX Zip: 77084

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

11 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
Hubbard, Keith		khubbard@p3petro.com	
,		michael.hickey@state.co.us	
Hoffman, John		john@p3petro.com	
Mustacchia, Joey		jmustacchia@p3petro.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
203687	WELL	SI	06/01/2019	OW	001-09247	UPV 27-7M4	SI

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	No sign		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	AG panel lying on the ground		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bradenhead	# 1		
Comment:	appears plumbed to surface		
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	automation		
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 2		
Comment:	cards indicate that calibration is not current		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		

Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	1	300 BBLS	STEEL AST		39.936170,-104.534560	
Comment:	No Sign at the TB					
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	<100 BBLS	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition		
Other (Content)		
Other (Capacity)	80 bbl	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:	Shares containment with crude tank				
Corrective Action:					Date:

Wells Served By Facilities Above

API Number
001-09247

AirsID

API Number	AirsID
------------	--------

Venting:

Yes/No	NO		
--------	----	--	--

Comment:			
Corrective Action:		Date:	
Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected FacilitiesFacility ID: 203687 Type: WELL API Number: 001-09247 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: SI

Corrective Action: _____

Date: _____

BradenHeadDate of Last Brhd Test: 10/28/2021Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0Fluid Type: NONEEnd Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____

Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action: Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Tuesday 3/1/2022 at approximately 1225 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection: Operator: Painted Pegasus Petroleum (3P) Location: UPV 27-7M4</p> <p>API # 05-001-09247</p> <p>County: Adams</p> <p>While there, I observed a wellsite and tank battery. Because P3 is not actively managing any of its Colorado Wells or Locations there is a direct threat to public health, safety and welfare, including the environment and wildlife resources. Therefore, the COGCC will undertake steps to, at a minimum, shut-in all of P3's wells and lock-out/tag-out P3's flow lines. COGCC may take additional actions to protect public health, safety and welfare, including the environment and wildlife resources, without providing advanced notice.</p> <p>During this inspection the following possible compliance issues were observed: no sign at TB and calibration of Gas meters. See attached photos.</p> <p>Location: mostly muddy, Weather: clear.</p> <p>This is a summary of the inspection report.</p>	revasr	03/01/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699305110	location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5678384