

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC PA-66S95W /32SWSE

Location ID: 334700



Photo #6042 from entrance to location.



Photo #6043 from entrance to location.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC PA-66S95W /32SWSE

Location ID: 334700



Photo #6044 Location lacks stabilization.



Photo #5872 from inspection #699804111 conducted on 2/4/22.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC PA-66S95W /32SWSE

Location ID: 334700



Photo #6045 Location lacks stabilization.



Photo #5873 from inspection #699804111 conducted on 2/4/22.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC PA-66S95W /32SWSE

Location ID: 334700



Photo #6046 Location lacks stabilization.



Photo #6047 Insufficient tacking control at entrance to location.