

HCW 24-24 Wellhead and Flowline Abandonment Sampling Photographic Log



Entrada Consulting Group, Inc.
October 2021

Photo 1

HCW 24-24 Wellhead and Flowline Abandonment Sampling Photographic Log



Entrada Consulting Group, Inc.
October 2021

Photo 2

HCW 24-24 Wellhead and Flowline Abandonment Sampling Photographic Log



HCW 24-24 Wellhead and Flowline Abandonment Sampling Photographic Log




HCW 24-24 Wellhead and Flowline Abandonment Sampling Photographic Log



Entrada Consulting Group, Inc.
October 2021

Photo 5

HCW 24-24 Wellhead and Flowline Abandonment Sampling Photographic Log



Entrada Consulting Group, Inc.
October 2021

Photo 6

HCW 24-24 Wellhead and Flowline Abandonment Sampling Photographic Log



Entrada Consulting Group, Inc.
October 2021

Photo 7

HCW 24-24 Wellhead and Flowline Abandonment Sampling Photographic Log



Entrada Consulting Group, Inc.
October 2021

Photo 8

HCW 24-24 Wellhead and Flowline Abandonment Sampling Photographic Log



Entrada Consulting Group, Inc.
October 2021

Photo 9