


Inspection Photos
Location Name: Joy 21-4
Location ID: 320088



Pic 1 at time of inspection master valve, and both casing valves were open, Flowlines were closed. Master valve, and casing valves were put in the close position at time of inspection.

Pic 2 Separator

Inspection Photos
Location Name: Joy 21-4
Location ID: 320088



Pic 3 Gas meter run

Pic 4 tanks, at time of inspection tanks appeared to have fluid inside.