

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/25/2022

Submitted Date:

03/03/2022

Document Number:

697503759

**FIELD INSPECTION FORM**

Loc ID 320644 Inspector Name: Binschus, Chris On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 74165  
Name of Operator: RENEGADE OIL & GAS COMPANY LLC  
Address: 6155 S MAIN STREET #225  
City: AURORA State: CO Zip: 80016

**Findings:**

- 4 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
		ed@renegadeoilandgas.com	
		jbcrog@aol.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
204243	WELL	SI	05/01/2020	OG	005-06327	Lowry State 13-25	RI

**General Comment:**

This is a follow up inspection to Doc.# 697502652 at the associated tank battery.

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type:	#		corrective date
Comment:	Operator has removed the unused risers observed along the southern tank battery. The equipment removal area that extends south to an old pit needs to be seeded. Refer to the attached inspection photos and refer to the Stormwater section for the corrective action.		
Corrective Action:			Date:

**Venting:**

Yes/No		
Comment:		
Corrective Action:		Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 204243 Type: WELL API Number: 005-06327 Status: SI Insp. Status: RI

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Operator has performed additional stormwater measures by recontouring portions of the tank battery, adding riprap as check dams, and repairing erosion off location. The repaired erosion area off location to the east of the tank battery needs to be seeded. Some rill erosion was observed along some of the repaired work area off location and should be repaired when performing seedbed prep.

Corrective Action: Comply with Rule 1002.f. to stabilize the stormwater repair work off location and the equipment removal area by performing additional seeding. Refer to Photo 1.

Date: 05/01/2022

Pits:  NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
COGCC Staff, Chris Binschus, discussed these observations and plans to perform additional seeding with the Operator on March 2, 2022 via a phone call.	binschusc	03/03/2022

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
697503760	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5680404">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5680404</a>