

Inspection Photos

Location Name: CAERUS PICEANCE LLC NOCKS-68S96W /2NENE

Location ID: 334078



Photo #6063 from entrance to location.



Photo #6064 from entrance to location.

Inspection Photos

Location Name: CAERUS PICEANCE LLC NOCKS-68S96W /2NENE

Location ID: 334078



Photo #6065 Location lacks stabilization.



Photo #3813 from inspection #699803080 conducted on 5/14/21.

Inspection Photos

Location Name: CAERUS PICEANCE LLC NOCKS-68S96W /2NENE

Location ID: 334078



Photo #6066 Location lacks stabilization.



Photo #3814 from inspection #699803080 conducted on 5/14/21.

Inspection Photos

Location Name: CAERUS PICEANCE LLC NOCKS-68S96W /2NENE

Location ID: 334078



Photo #6067 Insufficient tracking BMP at entrance to location.



Photo #3815 from inspection #699803080 conducted on 5/14/21.