

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/03/2022

Submitted Date:

03/03/2022

Document Number:

690009009

FIELD INSPECTION FORMLoc ID 336226 Inspector Name: Carlile, Craig On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 47120

Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

6 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Oxy		COGCCInspections@Oxy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
249663	WELL	SI	05/01/2021	GW	123-17466	UPRC 31-16K	TA
249731	WELL	SI	05/01/2021	GW	123-17534	UPRC 31-15K	SI
249840	WELL	SI	05/01/2021	GW	123-17643	UPRC 31-11K	SI
288463	WELL	SI	05/01/2021	GW	123-24582	HERMAN FEDERAL 37-31	SI

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date:

Overall Good: ☒

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Plunger Lift	# 3		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		,
Comment:	Battery location number: 302744				
Corrective Action:				Date:	

Paint

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:			Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 249663 Type: WELL API Number: 123-17466 Status: SI Insp. Status: TA

BradenHead

Date of Last Brhd Test: 01/29/2021 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 12 Fluid Type: Liquid Hydrocarbon

End Surf Csg Pressure: --

Comment:

Corrective Action:

Date:

Facility ID: 249731 Type: WELL API Number: 123-17534 Status: SI Insp. Status: SI

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder:

Comment: SI

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 01/29/2021 Annual Brhd Completed?

Last Brhd Test Results Initial Surf Csg Pressure: 5 Fluid Type: Water

End Surf Csg Pressure: --

Comment:

Corrective Action:

Date:

Facility ID: 249840 Type: WELL API Number: 123-17643 Status: SI Insp. Status: SI

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder:

Comment: SI

Corrective Action:

Date:

Facility ID: 288463 Type: WELL API Number: 123-24582 Status: SI Insp. Status: SI

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder:

Comment: SI

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<u>Routine wellhead inspection.</u> <u>Muddy conditions.</u>	carlilec	03/03/2022

Attached Documents

You can go to COGCC Images ([https://cogcc.state.co.us/weblink/](https://cogcc.state.co.us/webblink/)) and search by document number:

Document Num	Description	URL
690009010	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5680636