

Foundation Energy Management LLC, Hatheway 33-10

125-09056

Inspection #688312278

2/28/2022

Routine Field Inspection



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

**FOUNDATION ENERGY**  
HATHEWAY No. 33-10  
NW SE SEC. 10-1N-45W  
1/2 MI. W OF ROADS 34  
& Z & N INTO  
YUMA COUNTY, CO

FOUNDATION ENERGY, LLC  
24-HR EMERGENCY #: 1-866-767-3600  
IN CASE OF EMERGENCY CALL: 911  
CO OP#10112

**FOUNDATION ENERGY MANAGEMENT, LLC**  
**HATHEWAY 34-10**  
SWSE Sec. 10-T1N-R45W  
Rd. 34 & Z, West 1/4 Mile, N. into  
Yuma County, CO

**FOUNDATION ENERGY**

FOUNDATION ENERGY, LLC  
24-HR EMERGENCY #: 1-866-767-3600  
IN CASE OF EMERGENCY CALL: 911  
CO OP#10112

**FOUNDATION ENERGY**

**HATHEWAY No. 33-10  
NW SE SEC. 10-1N-45W  
1/2 MI. W OF ROADS 34  
& Z & N INTO  
YUMA COUNTY, CO**



24-HR EMERGENCY #: 1-866-767-3600  
IN CASE OF EMERGENCY CALL: 911  
CO OP#10112

Colorado Oil and Gas Conservation Commission  
40.06668, -102.38619, 3763.1ft, 23°  
02/28/2022 01:01:29 PM




Colorado Oil and Gas Conservation Commission  
40.06671, -102.38615, 3769.7ft, 73°  
02/28/2022 01:01:34 PM


ENERGY



Colorado Oil and Gas Conservation Commission  
40.06671, -102.38615, 3773.0ft, 64°  
02/28/2022 01:01:42 PM

A photograph showing a metal wellhead component, possibly a valve or fitting, mounted on a concrete surface. A circular metal ring is attached to the component. Below the component, a blue data sheet is visible, partially obscured by a white timestamp overlay. The timestamp reads: "Colorado Oil and Gas Conservation Commission", "40.0667, -102.38614, 3773.0ft, 303°", and "02/28/2022 01:02:23 PM".

Colorado Oil and Gas Conservation Commission  
40.0667, -102.38614, 3773.0ft, 303°  
02/28/2022 01:02:23 PM



Colorado Oil and Gas Conservation Commission  
40.06671, -102.38615, 3773.0ft, 360°  
02/28/2022 01:02:01 PM



Colorado Oil and Gas Conservation Commission  
40.06671, -102.38615, 3773.0ft, 137°  
02/28/2022 01:02:04 PM