

Inspection Photos
Location Name: Randall 32-10
Location ID: 320024



Pic 1 At time of inspection master valve, and casing valve were in open position. During inspection Master valve and casing valve were put in close position. Flowline valve is seized in the open position, casing valve, and tubing valve are both shut.

