

Inspection Photos
Operator: Morningstar Operating
API: 007-06287
Date: 2/28/2022



Photo 1. View of project area from the well pad entrance facing center.




Photo 2. View of the eastern project area from the southeastern corner facing northward. Vegetation is largely dormant/grazed at this time. Russian thistle debris needs to be removed and managed to prevent debris.



Photo 3. View of the southern project area from the southeastern corner facing westward.



Photo 4. View of unused tubing stored along the edge of the tank storage area.



Photo 5. View of reference area vegetation comprised of open pinyon and juniper woodland with grasses in the understory, partially irrigated, with smooth brome, western wheatgrass, and blue grama observed.