

Inspection Photos
Operator: Simcoe
API: 007-06165
Date: 2/28/2022



Photo 1. View of project area from the well pad entrance facing center.



Photo 2. View of the western project area from the southwestern corner facing northward. Revegetation such as rubber rabbitbrush, sand dropseed, and western wheatgrass observed.



Photo 3. View of the southern project area from the southwestern corner facing eastward.



Photos 4/5. View of erosional rilling observed within the western fill slope (multiple areas). Stabilization is needed here.



Photo 6. View of reference area comprised of pinyon and juniper woodland with sagebrush, blue grama, prickly pear, and snakeweed in the understory.