

Inspection Photos
Operator: Morningstar Operating
API: 007-06209
Date: 2/28/2022



Photo 1. View of project area from the well pad entrance facing center.



Photo 2. View of the southern project area from the southeastern corner facing westward. Revegetation is largely dormant and grazed at this time. Revegetation needs to be monitored during the active growing season and re-seeding conducted if needed.



Photo 3. View of the eastern project area from the southeastern corner facing northward.



Photo 4. View of Russian knapweeds observed within the interim reclamation area. Approx. 1000 individuals observed.



Photo 5. View of Russian thistle debris observed within the project area.



Photo 6. View wire/fencing debris (approx 75 ft long) within the eastern project area, needs to be removed.



Photo 7. View of reference area comprised of open grass field, largely dormant at this time. Western wheatgrass is observable.