

Inspection Photos
Operator: Simcoe
API: 007-06086
Date: 2/28/2022



Photo 1. View of project area from the well pad entrance facing center.



Photo 2. View of the southern project area from the southwestern corner facing eastward. Revegetation is progressing with dense rubber rabbitbrush, sand dropseed, and western wheatgrass.




Photo 3. View of unused electrical equipment observed in the northern project area.



Photo 4. View of reference area comprised of mixed rubber rabbitbrush, sagebrush shrubland with sand dropseed, western wheatgrass, and snakeweed.