

Inspection Photos
Operator: Simcoe
API: 007-06143
Date: 2/28/2022



Photo 1. View of project area from the well pad entrance facing center. Significant salt crust observed on the well pad surface.



Photo 2. View of revegetation in the eastern project area. Portions of this area appear salt affected>.



Photo 3. View of bare soils observed within the eastern project area. Revegetation needs to be assessed during the active growing season.



Photo 4. View of the southern project area from the southeastern corner facing westward. Revegetation is progressing with grasses similar to the reference area (irrigated grass field).



Photo 5. View of deep rutting up to 18 inches deep, observed on the access road, needing stabilization. Hard hat in place for scale.



Photo 6. View of reference area comprised of irrigated grassland with grasses and wetland species such as timothy, tall fescue, and cattails.