

Inspection Photos

03/02/2022

Operator: MARALEX RESOURCES INC - 53255

Location ID: 312658

Mesa County, CO

Aaron Trujillo
NW Reclamation Specialist
COGCC

Inspection Photos
Operator Name: MARALEX RESOURCES INC - 53255
Location ID: 312658



Photo 1: Photo left shows sign at wellhead remains illegible. Photo right shows capacity labels on tank remain inadequate.

Inspection Photos
Operator Name: MARALEX RESOURCES INC - 53255
Location ID: 312658



Photo 2: Photo taken from tank on the west end of the Location. Photo shows secondary containment BMP is not in proper functioning condition, or adequate in size to contain a spill from the tank. Photo also shows weed/vegetation establishment have not been removed from the tank containment.

Inspection Photos
Operator Name: MARALEX RESOURCES INC - 53255
Location ID: 312658



Photo 3: Photo shows vegetation/weeds have not been removed from around equipment.

Inspection Photos
Operator Name: MARALEX RESOURCES INC - 53255
Location ID: 312658



Photo 4: Photo provides example of Halogeton establishment on the location. This is a Colorado State listed noxious weeds that requires management.

Inspection Photos
Operator Name: MARALEX RESOURCES INC - 53255
Location ID: 312658



Photo 5: Photo taken from the Location entrance, facing south. Photo shows control measures to stabilize the production areas of the Location, and to mitigate tracking/sediment transport remains missing or insufficient.

Inspection Photos
Operator Name: MARALEX RESOURCES INC - 53255
Location ID: 312658



March 2, 2022
39.3041589N 108.27614329W



07-26-2021 14:09

Photo 6: Photos taken from the east end of the Location, facing south. Photo left dated 3/2/2022; photo right dated 7/26/2021. Photos show erosion degradation due to runoff from the location has continued since the previous inspection; control measures to manage runoff and minimize erosion degradation remain missing or insufficient on the Location.

Inspection Photos
Operator Name: MARALEX RESOURCES INC - 53255
Location ID: 312658



Photo 7: Photos taken from the east end of the Location, facing east. Photo left dated 7/26/2021; photos right 3/2/2022. Photo shows gully erosion degradation due to runoff from the location has continued since the previous inspection; control measures to manage runoff and minimize erosion degradation remain missing or insufficient on the Location.

Inspection Photos
Operator Name: MARALEX RESOURCES INC - 53255
Location ID: 312658



Photo 8: Photo taken from the east end of the Location, facing west. Photo shows erosion degradation due to runoff from the location has continued since the previous inspection; control measures to manage runoff and minimize erosion degradation remain missing or insufficient on the Location.

Inspection Photos
Operator Name: MARALEX RESOURCES INC - 53255
Location ID: 312658



Photo 9: Photo taken from the west end of the Location, facing north. Photo shows control measures to stabilize the production areas of the Location, and to mitigate tracking/sediment transport remains missing or insufficient.

Inspection Photos
Operator Name: MARALEX RESOURCES INC - 53255
Location ID: 312658



Photo 10: Photo shows trash debris observed on the south end of the Location.

Inspection Photos
Operator Name: MARALEX RESOURCES INC - 53255
Location ID: 312658



Photo 11: Photos taken from the northwest end of the Location. Photos 11-12 show vehicle travel from the production pad leading offsite north of the Location, and traveling to “V 2/10 Rd” northeast of the Location to the Location. This does not comport to 1002.e surface disturbance requirements.

Inspection Photos
Operator Name: MARALEX RESOURCES INC - 53255
Location ID: 312658



Photo 12: See comments under photo 11.