

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/28/2022

Submitted Date:

02/28/2022

Document Number:

701102786**FIELD INSPECTION FORM**Loc ID 314263 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 16700

Name of Operator: CHEVRON USA INC

Address: 760 HORIZON DRIVE STE 401

City: GRAND JUNCTION State: CO Zip: 81506

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

7 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Sanford, Anita	(970) 675-3842	Anita.Sanford@scoutep.com	<a href="#">All Inspections</a>
Thompson, Bud		BLThomps@BLM.gov	
Regulatory, Rangely		RangelyRegulatory@scoutep.com	<a href="#">All Inspections</a>

**General Comment:**[COGCC Routine Inspection Report Summary](#)[Location is in a High Priority Habitat Area.](#)[During this inspection the following compliance issues were observed:](#)

- [No evidence of tracking control BMP's.](#)

[Location shows signs of lack of stabilization BMP's in some areas \(rutting is present\).](#)[A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.](#)

**Location****Lease Road:**

Type	Access		
comment:	Access road is wet, soft, rutted. Lack of stability. See Storm water report.		
Corrective Action		Date:	

Overall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:	911	Date:	
Corrective Action:			

**Good Housekeeping:**

Type	TRASH		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

Type: Bradenhead	# 1		corrective date
Comment:			
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Tracking Pad	Fail	Tracking Pad	Fail			No evidence of tracking control BMP's
		Compaction	Fail			
Compaction	Fail					
Berms						

Comment: No evidence of tracking control BMP's  
Location shows signs of lack of stabilization BMP's in some areas (rutting is present).

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: 03/16/2022

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402968870	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5677174">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5677174</a>
701102787	Inspection 701102786 photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5677170">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5677170</a>