

Inspection Photos  
Operator: Simcoe  
API: 067-08733  
Date: 3/2/2022



Photo 1. View of project area from the well pad entrance facing center.



Photo 2. View of the eastern project area from the northeastern corner facing southward. Revegetation is progressing largely with smooth brome, western wheatgrass, and crested wheatgrass.



Photo 3. View of the northern project area from the northeastern corner facing westward. Working area is fenced.





Photo 4. View of reference area comprised of irrigated grass field with grasses such as smooth brome and western wheatgrass observed.